



ऑयल इंडिया लिमिटेड

(भारत सरकार का उद्यम) पंजीकृत कार्यालय: दुलियाजान, असम

Oil India Limited

(A Government of India Enterprise) Registered Office "Duliajan, Assam

प्लॉट. न. 19, सेक्टर 16-ए, नोएडा-201 301 उत्तर प्रदेश

Plot No. : 19, Sector 16-A, Noida-201 301, Uttar Pradesh

दूरभाष / Telephone : 0120-2419000 फैक्स / Fax : 0120-2488310

CIN : L11101AS1959GOI001148 ई-मेल / E-mail : oilindia@oilindia.in, वेबसाईट / Website : www.oil-india.com

Ref. No. OIL/SEC/32-33/NSE-BSE

Dated: 20.10.2023

National Stock Exchange of India Limited

Exchange Plaza,
Plot No. C/1, G Block,
Bandra Kurla Complex,
Bandra (E), Mumbai - 400 051

NSE Symbol: OIL

BSE Limited

Department of Corporate Service
Phiroze Jeejeebhoy Towers
Dalal Street
Mumbai - 400 001

BSE Security Code: 533106

Sub: Press Release- Miscreant Activity leads to uncontrolled flow of fluid (mainly water) from shut in well

Ref: Regulation 30 of the SEBI (LODR) Regulations, 2015

Sir/Madam,

Pursuant to Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015, Press Release dated 20.10.2023 on the above subject is submitted for your information & records please.

Thanking you,

Yours faithfully,
For Oil India Limited

(A.K. Sahoo)
Company Secretary &
Compliance Officer



Press Release

Miscreant Activity leads to uncontrolled flow of fluid (mainly water) from shut in well of OIL in Duliajan

Duliajan, 20 October 2023: Reportedly, miscreants have completely cut and stole the entire X-Mass tree above the adapter of OIL's well no. NHK-67 at Gazal Basti near Duliajan leading to uncontrolled flow of well fluids, mainly water, from the well head. The incident was reported at around 9:30 pm on 19th October 2023. OIL has lodged an FIR with the local Police and informed the District Administration Authority.

Located within a depleted reservoir in Bordubi area, the well was in shut in condition since 2016.

The Crisis Management Team (CMT) of Oil India Ltd. has been mobilised, while the Fire Tenders have been stationed at site and necessary measures are being taken up on an emergent basis to cap the well. An on-site task force is coordinating the activities on ground so as to control the water flow, cap and restore the well in close coordination with local authority.
