

MSIL: COS: NSE&BSE: 2021/09\_2

3<sup>rd</sup> September, 2021

Vice President

National Stock Exchange of India Limited

"Exchange Plaza", Bandra- Kurla Complex

Bandra (E)

Mumbai - 400 051

General Manager

Department of Corporate Services

BSE Limited

Phiroze Jeejeebhoy Towers

Dalal Street, Mumbai- 400 001

**Sub: Press Release**

Dear Sir,


Please find enclosed herewith as Annexure -"A", a copy of the press release being issued today.

Kindly take the same on record.

Thanking you,

Yours truly,

For **Maruti Suzuki India Limited**



Sanjeev Grover

Vice President &

Company Secretary

**MARUTI SUZUKI INDIA LIMITED**

**Head Office:**

Maruti Suzuki India Limited,

1, Nelson Mandela Road, Vasant Kunj,

New Delhi - 110070, India.

Tel: 011- 46781000, Fax: 011-46150275/46150276

E-mail id: [contact@maruti.co.in](mailto:contact@maruti.co.in), [www.marutisuzuki.com](http://www.marutisuzuki.com)

**Gurgaon Plant:**

Maruti Suzuki India Limited,

Old Palam Gurgaon Road,

Gurgaon - 122015, Haryana, India.

Tel: 0124-2346721, Fax: 0124-2341304

**Manesar Plant:**

Maruti Suzuki India Limited,

Plot No.1, Phase - 3A, IMT Manesar,

Gurgaon - 122051, Haryana, India.

Tel: 0124-4884000, Fax: 0124-4884199

**Press Release**

**Maruti Suzuki to proactively recall 181,754 units of some petrol variants of Ciaz, Ertiga, Vitara Brezza, S-Cross and XL6**

**New Delhi 3<sup>rd</sup> September 2021:** As a responsible corporate, keeping in mind customer safety, Maruti Suzuki India Limited today announced to proactively undertake a recall of some petrol variants of Ciaz, Ertiga, Vitara Brezza, S-Cross and XL6. This is to inspect for a possible defect in 181,754 units of these models manufactured between 4<sup>th</sup> May 2018 to 27<sup>th</sup> October 2020.

Recall campaigns are undertaken globally to rectify faults that may be potential safety defects.

In the interest of customers, Maruti Suzuki has decided to voluntarily recall the affected vehicles for inspection/replacement of Motor Generator Unit, free of cost. Affected vehicle owners would be receiving a communication from Maruti Suzuki authorized workshops.

The replacement of the affected part shall start from the first week of November 2021. Till then, customers are requested to avoid driving in water logged areas and direct water spray on electrical/electronic parts in vehicle.

Customers of suspected vehicles can also visit the '**Imp Customer Info**' section on the Company websites [www.marutisuzuki.com](http://www.marutisuzuki.com) (for Ertiga and Vitara Brezza) or [www.nexaexperience.com](http://www.nexaexperience.com) (for Ciaz, XL6 and S-Cross) and fill-in their vehicle's chassis number (MA3, followed by 14 digit alpha-numeric number) to check if their vehicle needs any attention. The chassis number is embossed on the vehicle ID plate and is also mentioned in the vehicle invoice/registration documents.