



ZENITH FIBRES LIMITED

ISO 9001:2015 COMPANY CIN: L40100MH1989PLC054580 URL: www.zenithfibres.com

Date: 13.09.2024

To,
BSE Limited
Corporate Relations Department,
Phiroze Jeejeebhoy Towers,
Dalal Street, Fort,
Mumbai - 400001

**Re: Zenith Fibres Limited
Scrip Code: 514266**

Sub: Intimation under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015

Dear Sir/Madam,

In accordance with Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("SEBI Listing Regulations"), we wish to inform you that our wind mill situated at Vejalpar, Village Khakhrechi, Taluka Maniya - Miyana, District Morbi, Gujarat, India, has temporarily ceased generating power due to its generator failure. Power generated from this wind mill had mainly captive consumption for manufacture of Polypropylene Staple Fibre ("PPSF").

The Company has promptly taken steps to address the issue and is working diligently to restore normal operation of the said windmill as quickly as possible. Please be assured that there will be no impact on PPSF production.

For detailed information as required as per SEBI Circular No. SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated July 13, 2023, please refer to Annexure - A.

Kindly take the above information on your record.

Thanking you,

Yours faithfully,
For Zenith Fibres Limited

Dharati Bhavsar
Company Secretary

Regd. Office: 311, Marol Bhavan, Marol Co-Op. Ind. Estate Ltd., M.V. Road, Andheri (E), Mumbai - 400059, Maharashtra, (India)
Tele: +91-22-40153860 E-mail: mumbai@zenithfibres.com
Corporate Office: 103 "Synergy House", Subhanpura Road, Vadodara - 390023, Gujarat, (India)
Tele: +91-265-228-3744 Tele/Fax: +91-265-228-3743 E-mail: baroda@zenithfibres.com
Plant: Block 458, P.O. Tundav, Taluka: Savli, District: Vadodara - 391775, Gujarat, (India)
Tele: +91-8780601186, 8780601179 E-mail: plant@zenithfibres.com



ZENITH FIBRES LIMITED

ISO 9001:2015 COMPANY CIN: L40100MH1989PLC054580 URL: www.zenithfibres.com

Annexure - A

Sr No.	Particulars	Details
1	Expected quantum of loss / damage cause	The Company is currently assessing the extent of loss or damage resulting due to the generator failure.
2	Whether loss / damage covered by insurance or not including amount	Yes, the loss / damage covered by insurance.
3	Estimated impact on the production / operations in case of disruption /strikes/lock outs	The wind mill has temporarily stopped generating power/operating due to a generator failure. There will not be no impact on production of PPSF.
4	Factory / unit where the disruption /strike/lock out takes place including reasons for such disruption /strike .	The wind mill situated at Vejalpar, Village Khakhrechi, Taluka Maniya - Miyana, District Morbi, Gujarat, India. Reason: Generator failure of the wind mill.

Regd. Office: 311, Marol Bhavan, Marol Co-Op. Ind. Estate Ltd., M.V. Road, Andheri (E), Mumbai - 400059, Maharashtra, (India)
Tele: +91-22-40153860 E-mail: mumbai@zenithfibres.com

Corporate Office: 103 "Synergy House", Subhanpura Road, Vadodara - 390023, Gujarat, (India)
Tele: +91-265-228-3744 Tele/Fax: +91-265-228-3743 E-mail: baroda@zenithfibres.com

Plant: Block 458, P.O. Tundav, Taluka: Savli, District: Vadodara - 391775, Gujarat, (India)
Tele: +91-8780601186, 8780601179 E-mail: plant@zenithfibres.com