



RESPONSIBLE CARE®
OUR COMMITMENT TO SUSTAINABILITY



DNL/138/BSE/787/2022
8th June, 2022

Department of Corporate Services
BSE Limited
Phiroje Jeejeebhoy Towers
Dalal Street
MUMBAI - 400 001

Dear Sir,

Scrip Code: 506401

Re: Information under Regulation 30 of the SEBI (LODR) Regulations, 2015 - Update on Fire Incidence at Nandesari, Gujarat

We refer to our earlier letter dated 2nd June, 2022 intimating about the incidence of fire around the warehouse section of Company's manufacturing site located at Nandesari, District Vadodara, in the State of Gujarat ('Plant').

In this regard, we would like to inform that the fire caused damage to warehouse / offices / some utilities and part of manufacturing facility of Sodium Nitrite that were facing the warehouse. All the other manufacturing facilities including other two streams of Sodium Nitrite are unaffected and in safe conditions. Stability studies and other assessments are simultaneously being conducted to reassure safe operations.

The Company is in the process of submitting necessary applications / documents as sought by various authorities in order to obtain necessary permissions to restart the Plant, at the earliest.

We shall further update upon receiving clearance from authorities and starting of operation of the Plant.

Kindly take the same on your record.

Thanking you,

Yours faithfully
For DEEPAK NITRITE LIMITED


Arvind Bajpai
Company Secretary



DEEPAK NITRITE LIMITED

CIN: L24110GJ1970PLC001735

Registered & Corporate Office:

Aaditya - I, Chhani Road, Vadodara - 390 024, Gujarat, India.

Tel: +91 265 276 5200/396 0200 | Fax: +91 265 276 5344

Investor Relations Contact: investor@godeepak.com

www.godeepak.com