



**Regd. Office: P.O. Duliajan, Dist. Dibrugarh, Assam-786602**  
**Corp Office: Plot No. 19, Sector 16-A, Noida-201301, Uttar Pradesh**  
**CIN: L11101AS1959GOI001148 Website: [www.oil-india.com](http://www.oil-india.com)**

Ref. No. OIL/SEC/32-33/NSE-BSE

Dated: 15.02.2024

<b>National Stock Exchange of India Limited</b> Exchange Plaza, Plot No. C/1, G Block, Bandra Kurla Complex, Bandra (E), Mumbai - 400 051  NSE Symbol: OIL	<b>BSE Limited</b> Department of Corporate Service Phiroze Jeejeebhoy Towers Dalal Street Mumbai - 400 001  BSE Security Code: 533106
--	---

Sub : **Press Release - Incident at OIL well plinth**

Ref : **Regulation 30 of the SEBI (LODR) Regulations, 2015**

Sir / Madam,

Pursuant to Regulation 30 of the SEBI (LODR) Regulations, 2015, Press Release dated 15.02.2024 on the above subject, is submitted herewith for your information & records please.

Thanking you,

Yours faithfully,  
**For Oil India Limited**

**(A.K. Sahoo)**  
Company Secretary &  
Compliance Officer

Encl: As above



*Press Release*

**Incident at OIL well plinth**

*Duliajan, 15 Feb, 2024:* An incident occurred at well plinth NHK 162 of OIL at Western Asset Mine in Assam at around 3:05 pm on 14.02.2024 during bleeding of hydrotest water through 2” bleed line. While opening the 2” valve fitted in the part of artery line connection, the said valve and the bleed line got unexpectedly dislodged causing fatal injury to one contractor employee working in the vicinity. The employee was immediately rushed to OIL hospital at Duliajan for medical treatment. Despite immediate medical attention, the employee succumbed to his injuries at 5:00 pm on 14.02.2024. Oil India deeply mourns the unfortunate death of the employee. An internal enquiry is being conducted for a thorough investigation and OIL is committed to taking all necessary measures to prevent recurrence of such accidents in the future.

\*\*\*\*\*