

**Date: 18<sup>th</sup> July, 2022**

**The National Stock Exchange of India Limited**

Exchange Plaza, Bandra Kurla Complex,  
Bandra East,  
Mumbai – 400 051

**(Scrip Code – SHIVAMAUTO)**

**The BSE Limited**

Phiroje Jeejeebhoy Towers  
Dalal Street Fort  
Mumbai – 400 001

**(Scrip Code – 532776)**

**Sub: Intimation regarding Spillage of Salt at Rohtak Plant on 18<sup>th</sup> July, 2022.**

**Ref: Disclosure under Regulation 30 of Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015.**

Dear Sir/Madam,

In terms of above referred regulation, it is hereby informed that an accident has occurred due to Spillage of Salt from Sealed Quench Furnace (SQF) at our Rohtak Plant, Haryana on 18<sup>th</sup> July, 2022 at around 7.30 a.m. IST. The cause of the Spillage of salt from SQF shall be assessed in due course of time. This unfortunate incident has resulted in two fatalities and one burn injury.

The assessment of the loss caused to machineries and materials is under process; however, such accident has no adverse impact on the production capacity or operations.

You are requested to take the same on record.

Thanking you.

Yours truly,

**FOR SHIVAM AUTOTECH LIMITED**



**PREETI SHARMA  
COMPANY SECRETARY**