

VEDL/Sec./SE/17-18/11

April 20, 2017

BSE Limited Phiroze Jeejeebhoy Towers Dalal Street, Fort Mumbai - 400 001 National Stock Exchange of India Limited "Exchange Plaza" Bandra-Kurla Complex, Bandra (East), Mumbai – 400 051

Scrip Code: 500295

Scrip Code: VEDL

Dear Sir(s),

<u>Sub: Intimation under Regulation 30 of Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015.</u>

Pursuant to Regulation 30 of Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015, please find enclosed herewith the update on the Aluminum and Power Operations of the Company.

We request you to kindly take the above information on record.

Thanking you,

Yours faithfully,

For Vedanta Limited

Bhumika Sood

**Company Secretary & Compliance Officer** 



## Vedanta Limited Incidents at Aluminum and Power Operations

## Jharsuguda-I smelter update

The 500kt plant-1 smelter at Jharsuguda had an unfortunate pot outage incident earlier this week. 228 pots out of the total 608 pots were damaged and taken out of production. The impacted pots will require to be repaired over the next few months, and put back into production. Timelines will be announced in due course.

## Talwandi Sabo Power Plant, Wholly Owned Subsidiary of the Company

A fire took place at the coal handling plant at the 1980 MW TSPL Power Plant in Punjab state earlier this week. This has resulted in a shut down of all three units of the power plant for around 60 days. The plant had achieved full ramp up during FY 2017, and had record availability of 85% in Q4 FY 2017.

There were no injuries in either incident. The operational teams at the respective locations are working towards rectification, and safe and expeditious restart of the affected facilities.

