

The General Manager,
Department of Corporate Services
BSE Ltd.
Phiroze Jeejeebhoy Towers,
Dalal Street,
Mumbai 400 001

March 08, 2025

Security Code : 532957
Security ID : GOKAKTEX

Subject: Intimation under Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 (“Listing Regulations”) - update on Fire incident at the Company’s Solar Power Plant

In continuation to our communication letter dated January 17, 2025; February 03, 2025; February 15, 2025; March 05, 2025 and March 07, 2025 regarding Fire incident at the Company’s Solar Power Plant, located at Gokak Falls - 591308, Taluka - Gokak, District - Belagavi, Karnataka, India. We wish to inform that the updates as required as per SEBI Circular no. SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated July 13, 2023, and SEBI Master Circular no. SEBI/HO/CFD/PoD2/CIR/P/2023/120 dated November 11, 2024, are mentioned in Annexure - I.

For Gokak Textiles Limited

Rakesh M. Nanwani
Company Secretary & Compliance Officer

Encl: As above

GOKAK TEXTILES LIMITED

Registered Office: #1, 2nd Floor, 12th Cross, Ideal Homes, Near Jayanna Circle,
Rajarajeshwari Nagar, Bengaluru - 560 098

Telephone No.: +91 80 29744077 / 29744078 **Website:** www.gokaktextiles.com

GSTIN: 29AACCG8244P1ZX **CIN:** L17116KA2006PLC038839

Annexure 'I'

- a) insurance amount claimed and realized by the listed entity for the loss/damage - **yet to be claimed**
- b) the actual amount of damage caused due to the natural calamity or other force majeure events - **the actual amount of damage is yet to be ascertained**
- c) Details of steps taken to restore normalcy and the impact of the natural calamity/other force majeure events on production or service, financials of the entity - For safety reasons Feeders from block no. 7 and 8 were isolated immediately after the inverter blast.

The fire affected four blocks within the Solar Power Plant premises:

Sr. No	Affected Block	Description
1	Block - 1	5 MW (Generating full capacity)
2	Block - 2	5 MW (Generating full capacity)
3	Block - 3	3.4 MW generation of 5 MW capacity
4	Block - 4	3.4 MW generation of 5 MW capacity
5	Block - 5	5 MW (Generating full capacity)
6	Block - 6	4 MW generation of 5MW capacity
7	Block - 7	5 MW (Generating full capacity)
8	Block - 8	One inverter (2.5MW) down. OEM (FIMER) is inspecting the inverter. On clearance from OEM engineer and other safety check one inverter (2.5MW) shall be cut in.

For safety reasons block 8 is isolated. With isolation the plant is at 30.8MW. With one inverter in block 8 cut in the installed capacity shall be 33.3MW.

In addition, revival steps in block 3 & 4 are in full swing with estimation of restoring to full capacity within a week.

GOKAK TEXTILES LIMITED

Registered Office: #1, 2nd Floor, 12th Cross, Ideal Homes, Near Jayanna Circle,
Rajarajeshwari Nagar, Bengaluru - 560 098

Telephone No.: +91 80 29744077 / 29744078 **Website:** www.gokaktextiles.com

GSTIN: 29AACCG8244P1ZX **CIN:** L17116KA2006PLC038839