



January 24, 2025

The General Manager,
Department of Corporate Services
BSE Ltd.
Phiroze Jeejeebhoy Towers,
Dalal Street,
Mumbai 400 001

Security Code : 532957
Security ID : GOKAKTEX

<u>Subject:</u> Intimation under Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("Listing Regulations") - update on Fire incident at the Company's Solar Power Plant

In continuation to our communication letter dated January 17, 2025 regarding Fire incident at the Company's Solar Power Plant, located at Gokak Falls - 591308, Taluka - Gokak, District - Belagavi, Karnataka, India. We wish to inform that the updates as required as per SEBI Circular no. SEBI/HO/CFD-PoD-1/P/CIR/2023/123 dated July 13, 2023, and SEBI Master Circular no. SEBI/HO/CFD/PoD2/CIR/P/2023/120 dated November 11, 2024, are mentioned in Annexure - I.

For Gokak Textiles Limited

Rakesh M. Nanwani Company Secretary & Compliance Officer

Encl: As above

GSTIN: 29AACCG8244P1ZX CIN: L17116KA2006PLC038839





Annexure 'l'

- a) insurance amount claimed and realized by the listed entity for the loss/damage yet to be claimed
- b) the actual amount of damage caused due to the natural calamity or other force majeure events the actual amount of damage is yet to be ascertained
- c) Details of steps taken to restore normalcy and the impact of the natural calamity/other force majeure events on production or service, financials of the entity For safety reasons Feeders from block no. 5,6,7 and 8 were isolated immediately. Blocks 5,6,7 & 8 faced partial damages on account of this incident.

The fire affected four blocks within the solar power plant premises:

Sr.	Affected	Description	
No	Block		
1	Block - 6	About 272 tables of 324 tables in the block affected	
2	Block - 5	About 49 tables of 321 in the block affected	
3	Block - 7	About 51 tables of 320 in the block affected	
4	Block - 8	About 84 tables of 318 in the block affected	

A total of 20 MW of power generation was affected. In the last couple of days the following capacity was taken online by identifying and isolating the damaged parts:

Sr. No	Block Number	Restored Capacity
1	5	3.75MW
2	7	2.25MW
3	8	2.25MW

Telephone No.: +91 80 29744077 / 29744078 Website: www.gokaktextiles.com

GSTIN: 29AACCG8244P1ZX CIN: L17116KA2006PLC038839