



PNC Infratech Limited

An ISO 9001 : 2015 Certified Company

Ref No: PNC/SE/16/20-21

Date: 20.06.2020

To,
The Manager
The Department of Corporate Services
BSE Limited
Floor 25, P.J. Towers,
Dalal Street, Mumbai-400 001
Scrip code:539150

To,
The Manager
The Listing Department
National Stock Exchange of India Limited
Exchange Plaza, Bandra Kurla Complex,
Bandra (East), Mumbai-400 051
Scrip code: PNCINFRA

Dear Sir,

Sub: Press Release

We send herewith a copy of Press Release that is being issued by the Company intimating occurrence of a fatal accident at Four laning of Aligarh - Kanpur section of NH - 91 in the state of Uttar Pradesh under NHDP Phase-IV (Package II from Bhadwas to Kalyanpur) on 19.06.2020, late evening.

We request you to take on record of the same.

Thanking you,

For PNC Infratech Limited

Tapar

Tapar Jain

Company Secretary & Compliance Officer

ICSI M. No.: A22603



Encl: a/a



Corporate Office : PNC Tower,
3/22-D, Civil Lines, Bypass Road,
NH-2, Agra-282002

Tel. : 91-562-4054400 (30 Lines)
91-562-4070000 (30 Lines)

Fax : 91-562-4070011

Email : ho@pncinfratech.com

Regd. Office : NBCC Plaza, Tower II,
4th Floor, Pushp Vihar, Sector-V, Saket
New Delhi--110017 (India)

Tel. : 91-11-29574800 (10 Lines)
91-11-29566511, 64724122

Fax : +91-11-29563844

Email : delhioffice@pncinfratech.com

Web : www.pncinfratech.com

CIN : L45201DL1999PLC195937



PNC Infratech Limited

New Delhi, June 20, 2020: PNC Infratech Limited intimates occurrence of a fatal accident at one of its construction projects namely 'Four laning of Aligarh - Kanpur section of NH - 91 in the state of Uttar Pradesh under NHDP Phase-IV (Package II from Bhadwas to Kalyanpur) on 19.06.2020, late evening, due to accidental fall of prestressed concrete girders from top of piers of a viaduct (flyover) under construction at km 227.160, near Manikpur. The rescue measures at the location got underway in time.

Only 300 m length of highway is affected due to the above incident and work at the remaining 44.8 km length of project highway is continuing unaffected.