GHCL Limited



June 9, 2023

National Stock Exchange of India Limited NSE Code: GHCL

BSE Limited BSE Code: 500171

Dear Sir/ Madam,

<u>Subject: Update on Restoration of Soda Ash Production - Regulation 30(4) of SEBI (LODR)</u> Regulations, 2015

With reference to our earlier communication dated March 3, 2023, and in compliance with Regulation 30(4) read with Para B of Part A of Schedule III to the SEBI (LODR) Regulations, 2015, we would like to provide an update on the mechanical breakdown incident in the lime kilns of our Soda Ash plant.

We are pleased to inform you that the mechanical breakdown issue has been successfully resolved, and the production of Soda Ash has now returned to normal levels, reaching the pre-breakdown capacity.

As soon as the breakdown occurred, we took immediate and decisive actions to restore normalcy in our production processes. One of the key steps we took was to make the standby lime kiln, which was undergoing commissioning, fully operational. Additionally, we have implemented the use of infrared thermal cameras to monitor the skin temperature of all lime kilns, as recommended by technical experts.

This proactive measure enables us to assess the health of the lime kilns and detect any anomalies at an early stage, thus mitigating the risk of future incidents.

We assure our shareholders that the Company remains committed to maintaining the highest standards of operational efficiency, safety, and risk management in all our manufacturing processes.

We request you to kindly take this update on record and disseminate it on the stock exchange website for the information of our shareholders, investors, and other stakeholders.

Thanking you

Yours faithfully

For GHCL Limited

Bhuwneshwar Mishra

Vice President – Sustainability & Company Secretary

B- 38, GHCL House, Institutional Area, Sector- 1, Noida, (U.P.) - 201301, India. Ph. : +91-120-2535335, 4939900, Fax : +91-120-2535209 CIN : L24100GJ1983PLC006513, E-mail : ghclinfo@ghcl.co.in, Website : ghclinfo@ghcl.co.in