



To,

July 24, 2023

National Stock Exchange of India Ltd. Exchange Plaza Bldg. 5 th Floor, Plot No.C-1 'G' Block, Near Wockhardt, Bandra Kurla Complex Mumbai 400 051 Fax:26598237/38 Symbol: DCW	BSE Limited Department of Corporate Services, 1 st floor, New Trading Ring Rotunda Building, Phiroze Jeejeebhoy Towers, Dalal Street, Mumbai - 400 001 Fax: 22723121/3719/2037/2039 Scrip Code: 500117
--	---

Dear Sir(s)/Madam,

Sub: Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 - Update on Restoration of operations at Sahapuram Plant

With reference to our earlier communication dated July 19, 2023, and in compliance with Regulation 30(4) read with Para B of Part A of Schedule III to the SEBI (LODR) Regulations, 2015 and other applicable provisions, if any, we hereby provide update on unexpected failure in the power plant at site.

We are pleased to inform that the failure in the power plant has been resolved at Sahapuram Plant and the plant has resumed its operations effective July 24, 2023.

We assure our shareholders that the Management is committed to maintain highest possible level of operational efficiency & risk management.

Further in terms of SEBI circular CIR/CFD/CMD/4/2015 dated September 9, 2015 read with Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulation, 2015 the additional information required is given in the Annexure - I.

Thanking You,

Yours faithfully,

For DCW Limited



Dilip Darji

Sr. General Manager (Legal) & Company Secretary

Membership No. ACS-22527

DCW LIMITED

HEAD OFFICE :

"NIRMAL" 3RD FLOOR, NARIMAN POINT, MUMBAI-400 021.

TEL.: 2287 1914, 2287 1916, 2202 0743 TELEFAX: 22 2202 8838

REGISTERED OFFICE : DHRANGADHRA - 363 315 (GUJRAT STATE)

Email: ho@dcwlimited.com, Website: www.dcwlimited.com, CIN-L24110GJ1939PLC000748



Annexure - I

Sr. No	Restoration of operations at Sahupuram, Tamilnadu Plant	
a	Insurance amount claimed and realized by the listed entity for the loss/damage;	Not Applicable
b	The actual amount of damage caused due to the natural calamity or other force majeure events;	The temporary disruption was due to unexpected failure in the power plant at the site and not due to any natural calamity or other force majeure events.
c	Details of steps taken to restore normalcy and the impact of the natural calamity/other force majeure events on production or service, financials of the entity.	The Company has rectified failure in the power plant at the site.



DCW LIMITED

HEAD OFFICE :

"NIRMAL" 3RD FLOOR, NARIMAN POINT, MUMBAI-400 021.

TEL.: 2287 1914, 2287 1916, 2202 0743 TELEFAX: 22 2202 8838

REGISTERED OFFICE : DHRANGADHRA - 363 315 (GUJRAT STATE)

Email: ho@dcwlimited.com, Website: www.dcwlimited.com, CIN-L24110GJ1939PLC000748