



ऑयल इंडिया लिमिटेड

(भारत सरकार का उद्यम) पंजीकृत कार्यालय: दुलियाजान, असम

Oil India Limited

(A Government of India Enterprise) Registered Office "Duliajan, Assam

प्लॉट. न. 19, सेक्टर 16-ए, नोएडा-201 301 उत्तर प्रदेश

Plot No. : 19, Sector 16-A, Noida-201 301, Uttar Pradesh

दूरभाष / Telephone : 0120-2419000 फैक्स / Fax : 0120-2488310

CIN : L11101AS1959GOI001148 ई-मेल / E-mail : oilindia@oilindia.in, वेबसाईट / Website : www.oil-india.com

Ref. No. OIL/SEC/32-33/NSE-BSE

Dated: 31.05.2023

National Stock Exchange of India Limited Exchange Plaza, Plot No. C/1, G Block, Bandra Kurla Complex, Bandra (E), Mumbai - 400 051 NSE Symbol: OIL	BSE Limited Department of Corporate Service Phiroze Jeejeebhoy Towers Dalal Street Mumbai - 400 001 BSE Security Code: 533106
--	---

Sub: Press Release on Fire Incident at Numaligarh Refinery Limited
[NRL] - Material Subsidiary of Company

Ref: Regulation 30 of the SEBI (LODR) Regulations, 2015

Sir/Madam,

Pursuant to Regulation 30 of the SEBI (LODR) Regulations, 2015, Press Release dated 30.05.2023 on the captioned subject, is submitted herewith for your information & records please.

Thanking you,

Yours faithfully,
For Oil India Limited

(A.K. Sahoo)
Company Secretary &
Compliance Officer

Encl.: As above



PRESS RELEASE

30.05.2023

NRL Fire

A fire broke out at the Numaligarh Refinery Limited's Hydrocracker Unit (HCU) in vessel Number VV-04 at approximately 19:20 hours on 29.05.2023. The vessel is a cold high-pressure separator. The fire was brought under control within 20 minutes of break out. However, as per firefighting protocol, cooling through water spraying is still being carried out.

Assessment of the damage has not been done yet. There is no personal injury or fatality in the incident. Nearby Hydrogen unit has been shut down as a precautionary measure.

An external investigation committee is being constituted to investigate the root cause of the incident and to ascertain the quantum impact of the incident.
