

## SpiceJet Limited

319 Udyog Vihar, Phase-IV, Gurugram 122016, Haryana, India. Tel: + 91 124 3913939 Fax: + 91 124 3913844

Through E-mail

June 4, 2022

Mr. Harshad Naik, Listing Compliance, BSE Limited, Phiroz Jeejeebhoy Towers, Dalal Street, Mumbai – 400001

Reference: Scrip Code: 500285 and Scrip ID: SPICEJET

Subject: Clarification regarding news article

Dear Sir,

This refer to your e-mail dated May 31, 2022 seeking clarification on news article appeared at <a href="https://www.businesstoday.in">https://www.businesstoday.in</a> titled as "DGCA imposes Rs.10 lakh fine on SpiceJet for training pilots on faulty simulator".

The Company has 650 pilots trained on MAX aircraft and DGCA had an observation on the training profile followed for 90 pilots. As per the advise of DGCA, the Company restricted these 90 pilots from operating MAX aircraft, until these pilots undergo re-training to the satisfaction of DGCA. This restriction does not impact the operations of MAX aircraft and the Company has adequate trained pilots available for its operations. Basis the observation of DGCA these 90 pilots shall undergo re-training. DGCA has imposed penalty of Rs.10 lakh basis its audit observations.

Hope the above clarifies.

Thanking you,

Yours truly, For SpiceJet Limited

Chandan Sand

Sr. VP (Legal) & Company Secretary