

Date: January 2, 2025

To BSE Limited Corporate Relationship Department 1st Floor, New Trading Ring, Rotunda Building, P.J. Towers, Dalal Street, Fort, Mumbai – 400 001 Scrip Code: 506390	To National Stock Exchange of India Limited Listing Department, Exchange Plaza, 5th Floor, Plot No. C/1, G Block Bandra- Kurla Complex, Bandra (East) Symbol: HEUBACHIND
---	---

Subject: Intimation regarding Fire Incident occurred at the Company Plant located in Roha, Maharashtra under Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 (“SEBI Listing Regulations”).

Dear Sir,

Pursuant to Regulation 30 read along with Para-B, Part-A of Schedule III of the SEBI Listing Regulations, it is hereby informed that on Wednesday, January 1, 2025, at approximately 19:55 HRS, fire broke out at the Company’s Plant, located at Plot No. 113/114, MIDC Dhatav, Near Police Station, Kolad–Roha Road , A.V. Roha A.V. P. O. - Dhatav, Taluka – Roha ,Dist.-Raigad 402 116, India. The warehouse is used for storage of pigment in process goods used for final manufacturing. There have been no injuries or casualties.

The team at our Factory with support from the neighbouring industries, got the situation under control around 20:45 hrs.

The Company is currently investigating the root cause of the incident and assessing the extent of damage. We will provide an update on our findings in due course.

Additionally, we would like to inform you that the company has adequate insurance coverage. The claim process with the insurance company has been initiated, and we have requested a surveyor to assess the situation. The Company is committed to ensuring the highest safety standards.

Additional details as per SEBI Circular no. SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated July 13, 2023, and SEBI Master Circular no. SEBI/HO/CFD/PoD2/CIR/P/2023/120 dated November 11, 2024, is mentioned in **Annexure-A**.

This is for your information and record.

Yours faithfully,
For **Heubach Colorants India Limited**

Ashwini Natekar
Company Secretary and
Compliance Officer - Interim
Place: Navi Mumbai

Annexure A

Details at the time of occurrence of Fire:

1.	Expected quantum of loss/damage caused	The Company is in the process of ascertaining the damage caused by the fire.
2.	Whether loss/damage covered by insurance or not, including amount	The damage caused due to the fire accident is adequately covered by the insurance. The Company holds a comprehensive IAR Policy with a sum assured of Rs. 932.52 Crores through an insurance provider.
3.	Estimated impact on the production/operations in case of strikes/lock outs	Production/Operations of the Factory is temporarily suspended due to the fire incident. Further, since the Company is in the process of ascertaining the damage caused by the fire, the estimated impact, if any, on the production / operations due to the fire will be intimated in due course.
4.	Factory/unit where the strike/lock out takes place including reasons for such strike	Fire broke out at Roha Plant, located at Plot No. 113/114, MIDC Dhatav, Near Police Station, Kolad–Roha Road , A.V. Roha A.V. P. O. - Dhatav, Taluka – Roha ,Dist.-Raigad 402 116, India.