

VARUN BEVERAGES LIMICED



Corporate Off: Plot No.31, Institutional Area, Sec.-44, Gurgaon, Haryana-122002 (India) Ph.: +91-124-4643100-500 • Fax: +91-124-4643303/04 E-mail : info@rjcorp.in • Visit us at : www.varunpepsi.com CIN No. : L74899DL1995PLC069839

November 22, 2022

Τo,

National Stock Exchange of India Ltd.	BSE Limited
Exchange Plaza, Block G, C/1, Bandra Kurla	Phiroze Jeejeebhoy Towers
Complex, Bandra (E), Mumbai – 400 051	Dalal Street, Mumbai – 400 001
Email: cmlist@nse.co.in	Email: corp.relations@bseindia.com
Symbol: VBL	Security Code: 540180

## Subject: <u>Reports in some sections of the media regarding gas leak in a</u> <u>manufacturing facility of Varun Beverages Limited at Sonarpur, West</u> <u>Bengal</u>

Dear Sir/Madam,

Varun Beverages Limited follows a high level of safety standards at all its manufacturing facilities without exception. The Company conducts regular preventive maintenance including annual maintenance at its plants.

During this process on 21<sup>st</sup> November, 2022, the Plate Heat Exchanger (PHE) caused a noticeable smell in the area towards security. As per the Company's SOP, the security set-off an alarm and listening the alarm, the staff followed the Company's SOPs to ensure complete safety and avoid any eventuality of mishap of any kind - human or assets.

Some conscientious locals also called fire brigade, police and other agencies who after ensuring the safety standards concluded that the situation was normal to everyone satisfaction and there was no mishap or any injury caused to anyone which was duly communicated to all.

You are requested to take the above on record.

Yours faithfully, For Varun Beverages Limited

Ravi Batra Chief Risk Officer & Group Company Secretary