

## **Hindustan Oil Exploration Company Limited**

'Lakshmi Chambers', 192, St. Mary's Road, Alwarpet, Chennai - 600 018. INDIA. ©: 91 (044) 66229000 • Fax: 91 (044) 66229011 / 66229012

E-mail: contact@hoec.com • Website: www.hoec.com CIN: L11100GJ1996PLC029880

September 24, 2023 By Online

The Listing Department
National Stock Exchange of India Ltd.,

"Exchange Plaza", Bandra Kurla Complex, Bandra (East), Mumbai – 400 051

Stock Code: HINDOILEXP

The Corporate Relationship Department BSE Limited

1<sup>st</sup> Floor, P. Jeejeebhoy Towers, Dalal Street, Mumbai – 400 001

Stock Code: 500186

Dear Sir/Madam,

Sub: Submission of information pursuant to Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015

In furtherance to our intimation dated 16 September 2023, we hereby inform that the flushing of the oil export line in Block B-80 is completed, and the company has re-commenced production from D-2 well on 23 September 2023.

We further inform that during the planned shutdown for the replacement of Under Buoy Hose, expected to be carried out in the month of November 2023, again an attempt will be made to clean the oil export line completely to avoid any obstruction in future.

Further, in terms of SEBI circular SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated July 13, 2023, the additional information required is given in Annexure - I.

We request you to kindly take the submission on records.

Thanking you,
Yours Sincerely,
For Hindustan Oil Exploration Company Limited

Deepika CS Company Secretary



## **Annexure I**

Expected quantum of loss/damage caused	Nil
Whether loss/damage covered by insurance of not including amount	Not Applicable
Estimated impact on the production/operations in case of strike/lockouts/disruption	Nil
Factory/unit where the strike / lockout / disruption takes place including reasons for such strike / lockout / disruption	Western offshore- B80 field