

प्लॉट. न. 19, सैक्टर 16-ए, नोएडा-201 301 उत्तर प्रदेश

Plot No.: 19, Sector 16-A, Noida-201 301, Uttar Pradesh

दूरभाष / Telephone : 0120-2419000 फैक्स / Fax : 0120-2488310

CIN: L11101AS1959GOI001148 ई-मेल / E-mail: oilindia@oilindia.in, वेबसाईट / Website: www.oil-india.com

Ref. No. OIL/SEC/32-33/NSE-BSE/Reg. 30

Dated: 20.07.2020

National Stock Exchange of India Ltd.

Exchange Plaza, Plot No. C/1, G Block, Bandra-Kurla Complex, Bandra (E), Mumbai - 400 051 BSE Ltd.

Department of Corporate Service, Phiroze Jeejeebhoy Towers, Dalal Street, Mumbai- 400 001

Scrip: OIL

Scrip: 533106

Sub: Press Release - Blowout in Gas Well of the Company at Baghjan,

Tinsukia District, Assam

Ref: Regulation 30 of the SEBI (Listing Obligations and Disclosure

Requirements) Regulations, 2015

Sir/Madam,

We write further to our press release dated 18.07.2020 on the captioned subject and submit herewith **Press Release dated 19.07.2020** for your information & records please.

Thanking you,

Yours faithfully, For Oil India Limited

(A.K. Sahoo) Company Secretary & Compliance Officer



Press Release Blowout in Gas Well of Oil India Limited at Baghjan, Tinsukia 19th July 2020

Environmental Impact Assessment

- Environmental Impact Assessment by M/s ERM: Impact Assessment study prior to Capping of well is completed. Next phase of study to be conducted post Capping operation.
- TERI study on Bioremediation of Sludge: Site preparation for bio remediation along the roadside from Kaliapani Bridge to Baghjan village is in progress.
- CSIR-NEIST Seismological Study: Recording is in progress for seismological study in the vicinity of Baghjan-5 well.
- IIT- Guwahati Study on Thermal Mapping & Sonic Measurement: The study could not be carried out yesterday due to blockade.

Preparation for Capping the Well

Blockade/Barricade by Locals: A barricade was erected by local villagers blocking the
road from well site since afternoon yesterday. More than 200 personnel from OIL, ONGC,
Alert, Schlumberger and other contractors working at site including OIL Directors were not
allowed to go out of the site after completing the day's work yesterday. After prolonged
efforts by OIL Management and District Authority, the barricade was removed but as late as
at 02.30 hours this morning.

Relief and Rehabilitation

Survey for Damage Assessment: Survey job for assessment of damage for compensation in Doomdooma Circle till 18.07.2020 is 596 however survey could not carried out yesterday due to blockade by local people. 29 more families were surveyed on 18.07.2020 making total family surveyed in Tinsukia Circle as 1155. Total number of families surveyed till 18.07.2020 both combined in Tinsukia and Doomdooma Circle is 1751.

Law and Order/Bandhs/Blockades etc.

Stoppage of Oil/Gas Wells of Baghjan EPS Continues: 14 numbers of oil & gas wells under Baghjan EPS are shut in since 07-07-2020. As a result, approx. 1.5-1.6 MMSCMD gas has gone out from the grid which ultimately led to curtailment of gas supply to all consumers. Additionally, there is a daily oil production loss to the tune of around 500 KL from these wells. The cumulative loss is 5185MT of Crude Oil and 17.62 MMSCM of Natural Gas in last 12 days.



• Blockades in Drilling and Work Over Locations Continue: Blockade at two drilling locations and three workover locations still continues since the beginning of June, 2020.

Impact on Oil/Gas Production due to Protests

Due to stoppage/blockades, there was production loss of 442 MT of Crude Oil and 1.62 MMSCM of Natural Gas as reported on 18-07-2020. Operations were disrupted in 14 Oil wells & 05 gas wells. Cumulative production loss since 27th May, 2020 due to bandhs and blockades: 14385 MT Crude oil, 29.59 MMSCM of natural gas.

