

Regd. Office: P.O. Duliajan, Distt. Dibrugarh, Assam-786602 Corp Office: Plot No. 19, Sector 16-A, Noida-201301, Uttar Pradesh CIN: L11101AS1959GOI001148 Website: www.oil-india.com

Ref. No. OIL/SEC/32-33/NSE-BSE/Reg. 30

Dated: 02.08.2020

National Stock Exchange of India Ltd.

Exchange Plaza, Plot No. C/1, G Block, Bandra-Kurla Complex, Bandra (E), Mumbai - 400 051 BSE Ltd.

Department of Corporate Service, Phiroze Jeejeebhoy Towers, Dalal Street, Mumbai- 400 001

Scrip: OIL Scrip: 533106

Sub: Press Release - Blowout in Gas Well of the Company at Baghjan,

Tinsukia District, Assam

Ref: Regulation 30 of the SEBI (Listing Obligations and Disclosure

Requirements) Regulations, 2015

Sir/Madam,

Further to our press release dated 31.07.2020 on the captioned subject, we submit herewith the Press Release dated 01.08.2020 for your information & records please.

Thanking you,

Yours faithfully, For Oil India Limited

(A.K. Sahoo) Company Secretary & Compliance Officer



# <u>Press Release</u> <u>Blowout in Gas Well of Oil India Limited at Baghjan, Tinsukia</u> 1<sup>st</sup> August 2020

### **Environmental Impact Assessment**

- TERI Study on Air Quality & Noise Level: Recording of data at already installed analysers and sample collection for monitoring of air quality and noise level are in progress.
- TERI study on Bioremediation of Sludge: Application of bio material has been started from yesterday in the affected areas from Plastic Park side to Baghjan blowout well. Clearing of site prior to bio remediation in wetland areas and site preparations for ex/in-situ bio remediation job in affected areas are also in progress.
- CSIR-NEIST Seismological Study: Seismological recording carried out by CSIR-NEIST has been completed. Data is being analysed for submission of final report. Other Geo-Physical monitoring is being continued by CSIR-NEIST.
- IIT- Guwahati Study on Thermal Mapping & Sonic Measurement: Interpretation of the
  collected data will be carried out using specialized software at IIT Guwahati and the report
  will be submitted soon.

## **Preparation for Capping the Well**

- Final Preparation for Capping Operation: In view of the developments yesterday, the experts are evaluating the situation and looking at alternatives. All efforts are being taken to control the well at the earliest.
- Final Preparation for Killing Operation: Well killing fluid is ready at site.
- Water Deluge System: All six numbers of High Discharge CMT Water Pumps are operational at site for spraying water to the well head during the operation. Total 8 nos. of water pumps are available for filling both the water reservoirs periodically.

## **Relief and Rehabilitation**

 Survey for Damage Assessment: Survey for assessment of damage for compensation in both Doomdooma and Tinsukia Circle is in progress. Number of families surveyed in Doomdooma and Tinsukia Circle till 31.07.2020 are 596 and 2140 respectively. Total number of families surveyed till 31.07.2020 both combined in Doomdooma and Tinsukia Circle is 2736.



### Law and Order/Bandhs/Blockades etc.

- Closure of Wells: Production still continues to be affected due to forceful closure of few Oil & Gas wells connected to Baghjan EPS.
- **Blockade at Drilling/Workover Locations**: Drilling and workover operation still continue to be affected due to forceful closure of operation at few of the locations.

# Impact on Oil/Gas Production due to Protests

Due to stoppage/blockades of several producing wells, there was production loss of 652 MT of Crude Oil and 1.53 MMSCM of Natural Gas as reported on 31-07-2020. Cumulative production loss since 27<sup>th</sup> May, 2020 due to bandhs and blockades: 19504 MT Crude oil, 46.41 MMSCM of natural gas.

\*\*\*\*\*\*\*

