



ऑयल इंडिया लिमिटेड  
(भारत सरकार का उद्यम)  
**Oil India Limited**  
(A Government of India Enterprise)

Regd. Office: P.O. Duliajan, Distt. Dibrugarh, Assam-786602  
Corp Office: Plot No. 19, Sector 16-A, Noida-201301, Uttar Pradesh  
CIN: L11101AS1959GOI001148 Website: [www.oil-india.com](http://www.oil-india.com)

Ref. No. OIL/SEC/32-33/NSE-BSE/Reg. 30  
Dated: 04.07.2020

**National Stock Exchange of India Ltd.**

Exchange Plaza,  
Plot No. C/1, G Block,  
Bandra-Kurla Complex,  
Bandra (E),  
Mumbai - 400 051

**BSE Ltd.**

Department of Corporate Service,  
Phiroze Jeejeebhoy Towers,  
Dalal Street,  
Mumbai- 400 001

**Scrip: OIL**

**Scrip: 533106**

**Sub: Press Release - Blowout in Gas Well of the Company at Baghjan,  
Tinsukia District, Assam**

Ref: Regulation 30 of the SEBI (LODR) Regulations, 2015

Sir/Madam,

We write further to our earlier press release announcements on the captioned subject. Pursuant to Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015, **Press Release dated 03.07.2020** on the above subject is submitted for your information & record please.

Thanking you,

Yours faithfully,  
For Oil India Limited

(A.K. Sahoo)  
Company Secretary &  
Compliance Officer

**Press Release**

**Blowout in Gas Well of Oil India Limited at Baghjan, Tinsukia**

**03<sup>rd</sup> July 2020**

**Environmental Impact Assessment**

- **Environmental Impact Assessment by M/s ERM:** Air quality monitoring and Noise level monitoring were carried out at Guijan side, while air quality monitoring was carried out at Baghjan side yesterday. Consultation with local people carried out as a part of the ecological survey in Bebejia, Motapung and Balijan area.
- **TERI Study on Air Quality & Noise Level:** Samples for monitoring air quality and noise level are being collected for analysis. Recording of data at already installed analysers is in progress.
- **TERI study on Bioremediation of Sludge:** Site preparation for bio remediation job is in progress depending on site condition. Debris clearance along the roadside from the blow out well towards Maguri Beel is in progress.
- **CSIR-NEIST Seismological Study:** Recording is in progress in the vicinity of Baghjan-5 well. Currently, 5 sets of sensors including an accelerometer are recording data.

**Preparation for Capping the Well:**

- **Debris Removal:** The debris removal activity was continued at site today since morning with continuous spraying /jacketing of water in the well plinth/debris. 6 loads of debris amongst others, including following major items were removed from the well plinth yesterday :
  - 2 nos. of fire tenders
  - 1 no. filtration unit
  - 1 no. cement mixing tank
  - 1 no. cementing pump with delivery lines
- **Readiness of Equipment at Site:** Refilling of water reservoir carried out. Standby equipment & accessories are ready for water filling. Depending on requirement, fabrication & repairing jobs are being carried out at the temporary workshop created near the site.
- **Shifting of Debris from Laydown Area:** Shifting of debris from debris Lay Down to Duliajan is in progress as per requirement. Shifting of 5 loads of debris to Duliajan completed yesterday.



- **Civil work at Site:** 40% of civil work for development of the new area for placing Kill Pumps near debris laydown area has been completed. Emergency escape route from Debris Laydown Area has been made.
- **Transferring equipment/material to the site:** Following materials are being transferred to site today.
  - 2 nos. Fire Monitors
  - 140 pieces of portadeck mats
  - One no. excavator
  - Smoke Tower
  - Heat Shields with accessories for Fire Monitors, Bull dozers etc.

Other equipment and materials are being transferred in a phased manner depending on requirement and site condition.

- **Servicing of Equipment at OIL's CMT Yard/ Engineering Workshop:** Servicing of standby engine/ pumps etc. is in progress.
- **Equipment/Material mobilized from outside:** All important equipment/ materials mobilized from outside reached Duliajan/Site.

### **Relief and Rehabilitation**

- Surveys for Assessment of damage for compensation by the committee constituted by District Administration are in progress. Assessments for 34 more families were conducted yesterday in Doomdooma Circle and 70 families in Tinsukia circle making total number of families surveyed till date in Doomdooma and Tinsukia Circle 856 families.

### **Impact on Oil/Gas Production due to Protests**

- Due to stoppage/blockades, there was production loss of 28 MT of Crude Oil and 0.02 MMSCM of Natural Gas as reported on 02-07-2020. Operations were disrupted in 03 Oil wells. Cumulative production loss since 27<sup>th</sup> May, 2020 due to bandhs and blockades: 9047 MT Crude oil, 11.59 MMSCM of natural gas.

### **Any other Issues**

- Mock drill of evacuation plan was successfully carried out on 02.07.2020 with the Helicopter services provided by Airforce.

\*\*\*\*\*

