



ऑयल इंडिया लिमिटेड

(भारत सरकार का उद्यम)

**Oil India Limited**

(A Government of India Enterprise)

Regd. Office: P.O. Duliajan, Distt. Dibrugarh, Assam-786602  
Corp Office: Plot No. 19, Sector 16-A, Noida-201301, Uttar Pradesh  
CIN: L11101AS1959GOI001148 Website: [www.oil-india.com](http://www.oil-india.com)

Ref. No. OIL/SEC/32-33/NSE-BSE/Reg. 30

Dated: 11.07.2020

**National Stock Exchange of India Ltd.**

Exchange Plaza,  
Plot No. C/1, G Block,  
Bandra-Kurla Complex,  
Bandra (E),  
Mumbai - 400 051

**BSE Ltd.**

Department of Corporate Service,  
Phiroze Jeejeebhoy Towers,  
Dalal Street,  
Mumbai- 400 001

**Scrip: OIL**

**Scrip: 533106**

**Sub: Press Release - Blowout in Gas Well of the Company at Baghjan,  
Tinsukia District, Assam**

Ref: Regulation 30 of the SEBI (LODR) Regulations, 2015

Sir/Madam,

We write further to our earlier press release announcements on the captioned subject. Pursuant to Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015, **Press Release dated 10.07.2020** on the above subject is submitted for your information & record please.

Thanking you,

Yours faithfully,  
For Oil India Limited

(A.K. Sahoo)  
Company Secretary &  
Compliance Officer

**Press Release**

**Blowout in Gas Well of Oil India Limited at Baghjan, Tinsukia**

**10<sup>th</sup> July 2020**

**Environmental Impact Assessment**

- **Environmental Impact Assessment by M/s ERM:** Environmental Impact Assessment by M/s ERM is in progress. Air quality monitoring was carried out in Baghjan and Guijan area on 09-07-2020, while noise level monitoring was carried out in Guijan side.
- **TERI Study on Air Quality & Noise Level:** Sample collection for monitoring of air quality and noise level is in progress for analysis.
- **TERI study on Bioremediation of Sludge:** Debris clearance as a part of site preparation for bio remediation job is being carried out along the roadside from the blow out well towards Maguri Beel.
- **CSIR-NEIST Seismological Study:** Recording is in progress for seismological study in the vicinity of Baghjan-5 well.

**Preparation for Capping the Well**

- **Debris Removal:** It has been pouring heavily at site. Cutting of substructure of the drilling rig started with the help of Magna Bar from yesterday. Debris removal activities are being carried out since morning today.
- **Deluge Water Supply:** All arrangement for deluge water supply completed. All three ONGC CMT Pumps and OIL CMT Pump No.3 are in operation. OIL CMT pump#01 & #02 are also ready for delivery. Arrangement for connecting 2 Nos Flexible hose (laid over natural water body from delivery header of OIL CMT Pump No: 1&2) to the distribution manifold and from Distribution manifold to the Monitors at entrance gate is in progress. Pump Station No.2 at the river bank is inundated with river water.
- **Transferring of debris from Debris Lay Down Area:** 7 loads of debris have been transferred from Debris lay Down Area at site to Duliajan yesterday.
- **Civil work at Site:** Civil works are continuously being carried out for regular maintenance and specific requirement.
- **Transferring equipment/material to the site:** Arrangement for transferring BOP Stack for well capping operation is in progress. Other equipment and materials are being transferred depending on requirement and site condition.
- **Servicing of Equipment at OIL's CMT Yard/ Engineering Workshop:** Unitization for one set of engine and high discharge water pump is completed and will be transferred to the site depending on site requirement. Based on site requirement, servicing of other equipment and fabrication jobs are being carried out at OIL's Workshop.



### **Relief and Rehabilitation**

- Surveys for Assessment of damage for compensation by the committee constituted by District Administration are in progress. Damage assessment for **532** families completed in Doomdooma Circle and **628** families in Tinsukia Circle till 09-07-2020. Total number of families assessed till 09-07-2020 is **1160**.

### **Law and Order/Bandhs/Blockades etc.**

- **Continued Blockade resulting in loss of Oil & Gas Production:** Blockade still continues at Baghjan EPS since afternoon hours of 7<sup>th</sup> July, 2020 severely affecting OIL's oil & gas production. OIL has already lost 1076 MT of Crude Oil and 3.92 MMSCM of Natural Gas from these highly producing wells in 3 days since afternoon of 07-07-2020.
- **Blockade in Drilling and Workover Rig:** Operation of drilling and workover activities are also blocked in 3 drilling locations and 2 workover locations.

### **Impact on Oil/Gas Production due to Protests**

- Due to stoppage/blockades, there was production loss of 452 MT of Crude Oil and 1.51 MMSCM of Natural Gas as reported on 09-07-2020. Operations were disrupted in 11 Oil wells & 05 gas wells. Cumulative production loss since 27<sup>th</sup> May, 2020 due to bandhs and blockades: 10408 MT Crude oil, 15.88 MMSCM of natural gas.

\*\*\*\*\*

