



ऑयल इंडिया लिमिटेड

(भारत सरकार का उद्यम) पंजीकृत कार्यालय: दुलियाजान, असम

Oil India Limited

(A Government of India Enterprise) Registered Office "Duliajan, Assam"

प्लॉट. न. 19, सैक्टर 16-ए, नोएडा-201 301 उत्तर प्रदेश

Plot No. : 19, Sector 16-A, Noida-201 301, Uttar Pradesh

दूरभाष / Telephone : 0120-2419000 फैक्स / Fax : 0120-2488310

CIN : L11101AS1959GOI001148 ई-मेल / E-mail : oilindia@oilindia.in, वेबसाईट / Website : www.oil-india.com

Ref. No. OIL/SEC/32-33/NSE-BSE/Reg. 30

Dated: 14.08.2020

National Stock Exchange of India Ltd.

Exchange Plaza,
Plot No. C/1, G Block,
Bandra-Kurla Complex,
Bandra (E),
Mumbai - 400 051

BSE Ltd.

Department of Corporate Service,
Phiroze Jeejeebhoy Towers,
Dalal Street,
Mumbai- 400 001

Scrip: OIL

Scrip: 533106

**Sub: Press Release - Blowout in Gas Well of the Company at Baghjan,
Tinsukia District, Assam**

Ref: Regulation 30 of the SEBI (Listing Obligations and Disclosure
Requirements) Regulations, 2015

Sir/Madam,

Further to our press release dated 12.08.2020 on the captioned subject, we submit herewith the Press Release dated 13.08.2020 for your information & records please.

Thanking you,

Yours faithfully,
For Oil India Limited

(A.K. Sahoo)

Company Secretary &
Compliance Officer



ऑयल इंडिया लिमिटेड

(भारत सरकार का उद्योग)

Oil India Limited

(A Government of India Enterprise)

Press Release

Blowout in Gas Well of Oil India Limited at Baghjan, Tinsukia

13th August 2020

Preparation for Capping the Well: As advised by Alert and ONGC team, considering the overall operational safety during well capping and well killing operation, it has been decided to fabricate a scissor-type 'C'-plate for placement of liquid resin on top of the slips in an attempt to create a temporary 'pack-off' of the annular section from exposure to direct well bore pressure upon closing of the BOP. Fabrication of this scissor-type 'C'-plate has already been completed at OIL's Engineering Workshop and also transferred to the site. The placement of resins would now be carried out in two instalments, each consuming around 24 hours as setting time. This entire process is expected to take around 72-96 hours. All efforts are being taken to control the well at the earliest. Treatment of killing fluid is in progress too at site.

Relief and Rehabilitation: A total of 2756 number of families have been surveyed for assessment of damage for compensation till 12.08.2020 in Doomdooma and Tinsukia Circle put together.

Law and Order/Bandhs/Blockades etc.: Oil & Gas Production still continues to be affected due to forceful closure of few Oil & Gas wells connected to Baghjan EPS. Drilling and workover operation also continue to be affected at few of the locations due to forceful closure of operation.

Impact on Oil/Gas Production due to Protests: A total of 26923 Metric Tonnes of Crude Oil and 64.44 Million Metric St. Cubic Meter of Natural Gas have been lost respectively as a result of protests/blockades/ bandhs in and around Baghjan area since 27th May, 2020 due to the Blowout.

Environmental Impact Assessment: Environmental Impact Assessment (EIA) study on various parameters are being carried out by various agencies, viz. M/s TERI, M/s ERM, M/s CSIR-NEIST, IIT-Guwahati apart from OIL's in-house monitoring of Air quality/Noise level/Gas presence. Bio remediation activities at affected areas are also in progress.

